Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080150-7

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11585

RECEIVED FROM PLANT #9

DATE REC'D. 3-14-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		63		22					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
12	720145-2 Rectifier	12		
	IPS #04749			

RECEIVED BY HMC-1088 [signature]

INSPECTED BY [signature] DATE 3/13/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST. PASADENA, CALIF.

No. 11588

RECEIVED FROM PLANT #9

DATE REC'D 3-14-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		015	0	21					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
37	736225-1 Flange Assembly Spools	37		
35	736225-2 Flange Assembly Spools	35		
	IPS #04742			

RECEIVED BY HMC-1088 [signature]

INSPECTED BY [signature] DATE 3/13/57

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080150-7